

Work Order ID 153217

Thursday, November 10, 2016 1:54:48 PM

153217**U/R**

Ship DEC. 01

Page 1

Item ID: D119-646-112

Accept

N900040100

Setup Start

NS1

Revision ID: URF 15-560

Stop

NS2

Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016 Start Qty: 1.00

1


Cust Item ID:

Required Date: 11/24/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: 

Date: 11-11-10

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D119-646	C								

100

100

DC

Doc.Control -USB or Paperwork

Memo

Photocopy bluefile & type labels per PPP D119-646-112
CHG 004

0.00

0.00

0.00

0.00

0.00

110

110

Packaging

Packaging

Pick Kit

Memo

QC4- 100% Inspect kits for completeness

120

120

QC

Quality Control

Memo

B152550

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
933 2023		933 2023		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Work Order ID 153217

Thursday, November 10, 2016 1:54:48 PM

153217

Page 2

Item ID: D119-646-112 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: URF 15-560 Stop ***NS2***
Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH
Start Date: 11/21/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 11/24/2016 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
130									
Packaging	Memo	0.00				DAS 28 9-89	DAS 27 9-89	NOV 16 2016	
Packaging	Identify and pack for shipping as per PPP D119-646-112 Location: _____ PPP rev: _____								
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.00					DAS 21 9-89	NOV 18 2016	
Quality Control									
							DAS 21 9-89	NOV 18 2016	

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : _____					

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 1

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP RevA: New issue DD verified by:EC
12.11.05 raise to chg002 (ECN 12-675) DD verf:JLM IPP REV:B
raise to chg003 (ECN 13-534) DD verf:JLM IPP REV:C 13.03.20
14.11.25 IIN REV:C
(ECN 14-628) DD verf:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D119-646-141		Manufactured	No			110	Each	0.0000	1	1			
D119-646-141									**				
AW119 Replacement Skidtube with Standard Wearplates & Wearpads, Fits LH & RH													
D119-646-311		Manufactured	No			110	Each	4.0000	1	1			
D119-646-311									**				
Ground Handling													
					<u>Location</u>			<u>Loc Qty</u>		<u>Loc Code</u>			
					ST636a			4					
					152317			4					
D3883-2		Manufactured	No			110	Each	4.0000	2	2			
D3883-2									**				
Saddle, Outside RH													
					<u>Location</u>			<u>Loc Qty</u>		<u>Loc Code</u>			
					ST404			4					
					151994			4					
D3884-2		Manufactured	No			110	Each	4.0000	2	2			
D3884-2									**				
Saddle, Inside RH													
					<u>Location</u>			<u>Loc Qty</u>		<u>Loc Code</u>			
					ST404			4					
					151964			4					

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval 	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____							
Misidentified	☐	Past Due	☐								

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 2

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

D2652

Manufactured No

110

Each

570.0000

16

16

D2652

Bushing

**

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FG

44

31985

44

ST010

116

152312

116

ST012a

410

150988

410

AN3C50A

Purchased

No

110

Each

67.0000

8

8

AN3C50A

Bolt

**

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST346

67

m136025

67

AN4C6A

Purchased

No

110

Each

541.0000

12

12

AN4C6A

Bolt

**

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FG

14

103344

4

121657

10

OVER002

425

m135603

75

m135979

50

m136047

300

ST345

102

m135297

10

m135470

92

Thursday, November 10, 2016 1:54:47 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval																																																										
Description Work Order Deviation				Disposition				Completed By																																																									
								Lead hand / Supervisor Approval Verification																																																									
								QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 3

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

MS21250-05-006

Purchased

No

110

Each

54.0000

8

8

MS21250-05-006

BOLT

**

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FG

10

124291

10

ST295

44

M133234

30

M133606

14

NAS1149C0332R

Purchased

No

110

Each

4,114.000

8

8

NAS1149C0332R

WASHER

**

NOV 15 2016

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FP001

800

m135948

800

GA

86

m133284

86

ST260a

2068

m135466

1000

m135672

568

m136042

500

ST266

1160

m135408

460

m135766

500

m135908

200

Thursday, November 10, 2016 1:54:47 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 4

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

NAS1149C0432R

Purchased

No

110

Each

1,215.000

24

24

NAS1149C0432R

WASHER

**

NOV 15 2016

DAS 6 27
9-89 9-89

DAS 28
9-89

Location

Loc Qty

Loc Code

GA

373

m134676

373

ST266

842

m135979

842

110

Each

339.0000

8

8

NAS1149C0532R

Purchased

No

NAS1149C0532R

WASHER

**

NOV 15 2016

DAS 6 27
9-89 9-89

DAS 28
9-89

Location

Loc Qty

Loc Code

GA

50

116513

50

ST266

289

m135671

5

m135390

184

m135966

100

Thursday, November 10, 2016 1:54:47 PM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 5

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

MS21043-3

Purchased

No

110

Each

857.0000

8

8

MS21043-3

Nut

**

DAS 27
6 9-89

NOV 15 2016

DAS 28
9-89

Location

Loc Qty

Loc Code

CCK007

400

m135864

400

FG

80

103691

80

FP001

11

m130673

11

GA

45

m133990

45

ST302

252

m135704

252

ST304

69

m131340

69

MS21043-4

Purchased

No

110

Each

400.0000

13

13

MS21043-4

Nut

**

DAS 27
6 9-89

NOV 15 2016

DAS 28
9-89

Location

Loc Qty

Loc Code

FG

40

104603

40

GA

17

m132803

17

ST302

343

m135600

343

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 6

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

D2712

Manufactured No

110

Each

262.0000

12

12

D2712

Set Screw

**

NOV 15 2016

DAS 27
6 9-89

Location

Loc Qty

Loc Code

FG

50

29962

50

ST010

212

140532

9

149832

43

151290

50

152321

100

89929

10

D3672-3

Manufactured No

110

Each

860.0000

24

24

D3672-3

Washer, Phenolic

**

NOV 15 2016

DAS 27
6 9-89

Location

Loc Qty

Loc Code

FG

100

133083

52

134449

48

FP001

213

132639

213

ST049

47

149295

47

ST051A

500

151298

500

Thursday, November 10, 2016 1:54:47 PM

Shop Packet Print

Page 6

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step # : _____		QTY Effective : _____				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : _____							

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 7

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

D3672-7

Manufactured No

110

Each

865.0000

24

24

D3672-7

Washer, Phenolic

**

NOV 15 2016 DAS 27 6 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

FG

40

129987

25

133986

15

ST049

325

150867

325

ST051A

500

152458

500

24

D3407-041

Manufactured No

110

Each

4.0000

1

1

D3407-041

Tow Ring

**

NOV 15 2016 DAS 27 6 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

st530

4

151431

4

D3417-5

Manufactured No

110

Each

63.0000

2

2

D3417-5

Washer

**

NOV 15 2016 DAS 27 6 9-89

DAS 28 9-89

Location

Loc Qty

Loc Code

ST035

23

149255

23

ST038A

40

151493

40

2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Thursday, November 10, 2016 1:54:47 PM

Page 8

Work Order ID: 153217

153217

Parent Item: D119-646-112

D119-646-112

Parent Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH

Start Date: 11/21/2016

Required Date: 11/24/2016

Start Qty: 1.00

Required Qty: 1.00

D3456-1

Manufactured No

110

Each

92.0000

1

1

D3456-1

Washer

NOV 15 2016

DAS 6

9-89

DAS 27

9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

FG

7

25701

7

ST037

85

150652

36

151938

49

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Work Order ID 153217

Monday, November 14, 2016 9:10:33 AM

153217

Page 1

Item ID: D119-646-112 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: URF 15-560 Stop ***NS2***
Item Name: AW119 Skidtube with Standard Wearplates & Wearpads - RH
Start Date: 11/21/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 11/24/2016 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
IIN-D119-646	C

100

0.00

100

DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile &type labels per PPP D119-646-112
CHG 004DAS
21 NOV 14 2016
9-89

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.00

Quality Control

Item	Qty -011	Qty -012	Qty -111	Qty -112	Qty -211	Qty -212	Qty -041	Qty -141	Qty -151	Qty -241	Qty -251	Qty -311	Part Number	Description
69	24	24	24	24	24	24							AN960C416L	WASHER (OR NAS1149C0432R)
70	8	8	8	8	8	8							AN960C516L	WASHER (OR NAS1149C0532R)
71	8	8	8	8	8	8							MS21043-3	NUT
72	12	12	12	12	12	12							MS21043-4	NUT
73	12	12	12	12	12	12							D2712	SET SCREW
74	16	16	16	16	16	16							D3672-7	WASHER
75	24	24	24	24	24	24							D3672-3	WASHER
76	8	8	8	8	8	8							D3672-7	WASHER
80	1	1	1	1	1	1							D3407-041	TOW RING
81	2	2	2	2	2	2							D3417-5	WASHER
82	1	1	1	1	1	1							D3456-1	WASHER
83	1	1	1	1	1	1							MS21043-4	NUT
90												2	D3886-041	LUG ASSEMBLY
91												8	D2652	BUSHING
92												4	AN3C46A	BOLT
93												4	AN960C10L	WASHER (OR NAS1149C0332R)
94												4	MS21043-3	NUT

• COPYRIGHT © 2009 BY DART AEROSPACE USA, INC. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: C
Date: 13.08.16

6.0 PARTS LIST

6.1 Standard Skidtubes

Item	Qty -011	Qty -012	Qty -111	Qty -112	Qty -211	Qty -212	Qty -041	Qty -141	Qty -151	Qty -241	Qty -251	Qty -311	Part Number	Description
	X												D119-646-011	STANDARD SKIDTUBE INSTALLATION WITH WEARPADS, LH
		X											D119-646-012	STANDARD SKIDTUBE INSTALLATION WITH WEARPADS, RH
			X										D119-646-111	STANDARD SKIDTUBE INSTALLATION WITH FULL LENGTH WEARPLATES & WEARPADS, LH
				X									D119-646-112	STANDARD SKIDTUBE INSTALLATION WITH FULL LENGTH WEARPLATES & WEARPADS, RH
					X								D119-646-211	STANDARD SKIDTUBE INSTALLATION WITH TRAINING WEARPLATES, LH
						X							D119-646-212	STANDARD SKIDTUBE INSTALLATION WITH TRAINING WEARPLATES, RH
	1	1					X						D119-646-041	REPLACEMENT STANDARD SKIDTUBE WITH WEARPADS
			1	1				X					D119-646-141	REPLACEMENT STANDARD SKIDTUBE WITH FULL LENGTH WEARPLATES & WEARPADS
									X				D119-646-151	WEARPLATE KIT STANDARD SKIDTUBE
					1	1				X			D119-646-241	REPLACEMENT STANDARD SKIDTUBE WITH TRAINING WEARPLATES
											X		D119-646-251	TRAINING WEARPLATES STANDARD SKIDTUBE
	1	1	1	1	1	1						X	D119-646-311	GROUND HANDLING KIT
1							1						D3887-041	STANDARD SKIDTUBE ASSY. WITH WEARPAD
20								1					D3887-043	STANDARD SKIDTUBE ASSY. WITH WEARPLATE & WEARPAD
26									1				D3847-043	FWD WEARPLATE ASSY
27									1				D3847-045	CENTER WEARPLATE ASSY
28									1				D3847-047	AFT WEARPLATE ASSY
29									5				D3847-1	WEARPAD
30									1				D3847-11	WEARPAD
31									30				AN3C5A	BOLT
32									30				AN960C10L	WASHER (OR NAS1149C0332R)
40										1			D3887-045	STANDARD SKIDTUBE ASSY. TRAINING WEARPLATE
44											1		D3849-041	FWD TRAINING WEARPLATE ASSY
45											1		D3849-043	AFT TRAINING WEARPLATE ASSY
51											16		D3904-1	WASHER
52											8		AN3C46A	BOLT
53											8		MS21043-3	NUT
60	2		2		2								D3883-1	SADDLE, OUTSIDE, LH
61		2		2		2							D3883-2	SADDLE, OUTSIDE, RH
62	2		2		2								D3884-1	SADDLE, INSIDE, LH
63		2		2		2							D3884-2	SADDLE, INSIDE, RH
64	16	16	16	16	16	16							D2652	BUSHING
65	8	8	8	8	8	8							AN3C50A	BOLT
66	12	12	12	12	12	12							AN4C6A	BOLT
67	8	8	8	8	8	8							MS21250-05006	BOLT
68	8	8	8	8	8	8							AN960C10L	WASHER (OR NAS1149C0332R)

• COPYRIGHT © 2009 BY DART AEROSPACE USA, INC. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision: **C**
Date: 13.08.16